

CERTIFICATE OF STABILITY

1. Name of the school : Bappuji Hr.secondry school
2. Town& district : Prali check post,parali,palakkad
In which the school situated
3. Building details : Blk.no 1-sheet roof building
8 class rooms(413.35m²)
: Blk.no 2-sheet roof building
5 class rooms(258.54m²)
: Blkno 3- sheet roof building
3 class rooms(140.27m²)
: Blkno 4- Rcc building G+2
12 class rooms(909.69m²)
: Blkno 6- Rcc building G+3
11 class rooms(960.06m²)
:Blkno 7- Rcc building
2 class rooms(186.06m²)
4. Other Infrastructures
- Possibility of flooding : Nil
- Proximity to civic amenities : Available
- Proximity to Parking : Available
- Proximity to surface communication : Available
- Availability of water/electricity : Available
- Availability of Toilet facilities : Available

I certified that I have inspect the Bappuji higher secondry school building on 02-07-2022 referred to above and examined the various parts including the foundation with special reference to the classrooms. I am of the opinion that the all buildings are in accordance with the plans. These buildings are structurally sound and their stability will not be endangered by their use as school for the coming academic year.

Place: Palakkad

Date: 04-07-2022


AMARNATH. M.
M.E, Structural Engineer

AMARNATH. M
Registered Engineer-A
Reg.No: E-2050/08/9717/KKD/43/2017/EA
Department of Urban Affairs
Government of Kerala